

DP323

Lsch 1/100

Hsch 1/100

V—vlak

2.00m.

braak (woning in aanbouw)

linkerkruin

os

rechterkruin

okker

Vaste bodem	6.22	6.24	6.26	6.30	6.34	6.35	6.37	6.35	6.34	6.25	5.96	5.97	5.43	4.93	3.91	3.83	3.90	3.90	3.90	4.74	6.29	6.17	6.24	6.32	6.35	6.32	6.30	6.28	6.26	6.24	6.34
Slibbodem														4.93	4.66	4.54	4.59	4.56	4.74												
Tussenafstand		2.50	2.50	2.50	2.50	2.50	2.50	2.50	2.50	2.50	0.63	0.77	0.87	0.94	0.85	0.84	0.59	0.73	0.65	2.50	2.50	2.50	2.50	2.50	2.50	2.50	2.50	2.50	2.50	2.50	
Samengestelde afstand	-29.90	-27.40	-24.90	-22.40	-19.90	-17.40	-14.90	-12.40	-9.90	-7.40	-4.90	-4.26	-3.49	-2.63	-1.69	-0.84	0.00	0.59	1.32	1.98	4.48	6.98	9.48	11.98	14.48	16.98	19.48	21.98	24.48	26.98	